BID PROPOSAL

Biditem	Description	Quantity	Units	Unit Price	Bid Total
PCO2-1	Replace all Beam Bolts				16,200.00
PCO2-2	Perform Beam Repairs				62,600.00
PCO2-3	Install 18 new Columns				98,550.00
PCO2-4	Coat New Columns				13,806.00
PCO2-5	Caulk Column Holes				6,450.00
PCO2-6	Coat all Anchors				5,150.00
	Bid Total				\$202,756.00

QUOTATION REQUEST DIGESTER 2 COVER REHABILITATION PROJECT

Contract Number: Date: 8/15/2019 I100103-2721 / PWP No. WA-2019-112

Jeff Farr Resource Development Co. 1050 Linda Way Sparks, NV 89431

Quotation Request No. 1

Title: Structural Steel Repairs

Reason for Change:

Steel columns and beams within the Digester have deteriorated due to corrosion and need to be repaired.

This Quotation Request is issued to request that Resource Development Co. provide any additional costs and credits necessary to prepare a Change Order based on the following:

- 1. Replace all beam bolts with A307 bolts to match the existing bolts size and length throughout the Digester cover.
- 2. Perform Beam Repairs as marked in chalk in the field. Top chord repairs were marked on the beam web on the side to be repaired. Bottom flange repairs were marked on the bottom of the beam. Perform repairs as indicated in drawing SK-1.
- 3. Install 18 new columns to match the existing columns. The new columns shall be installed on the existing empty corbels. A drawing of the existing columns, detail A in drawing 30-S-B, is included for reference from the structural engineer. Columns shall match the existing columns, except the existing corbels shall not be drilled into. Delete the anchors in the base of the column. Install grout between the column base and corbel. Scan the concrete wall to locate existing rebar prior to drilling into the existing concrete wall. Rebar shall not be cut to install concrete anchors. Each column has 6 horizontal concrete anchors.
- 4. New columns shall be coated with System 1, 100% solids elastomeric polyurethane, or System 2, epoxy per specification 09800. If system 1 is chosen it should be applied prior to installing the columns.
- 5. Existing column holes due to corrosion shall be caulked, coated with system 2 in specification 09800, and remain in place.
- 6. Coat all anchors after installation.

Please review enclosed attachments, details and or applicable plans and specifications with respect to this request for any changes in work or contract amount.

Please note all requests for lump sum prices must be itemized with units of labor, quantities of materials, overhead and profit clearly identified. Attach subcontractor or supplier information and quotations as applicable. Please respond to this request by August 20th, 2019.


This request is not a notice to proceed with the indicated work. If additional information is required or you have any questions regarding this request, please contact Ryan Owens.


Regards,

Ryan Owens <u>ROwens@brwncald.com</u> 775-525-4514

QUOTATION REQUEST DIGESTER 2 COVER REHABILITATION PROJECT

cc: Roy Johnson, Steve Gamilis, George Ghusn





Copyright 2018-2019. All rights reserved BJG | Architecture + Engineering. This drawing is the property of BJG and may not be reproduced without the express written authorization from BJG | Architecture + Engineering.